

Dams Safety NSW



Local government forum

Fairfield's high risk dams

Dams Safety NSW



Leonie Gray

- Catchment Planning Manager
- Fairfield City Council







Fairfield's high risk dams

Flood Detention Basins











Three tributaries FRMS&P

- Mostly grassed embankments, no dedicated spillways
- Geotechnical report: basin overtop = likely failure
- Dambreak assessments
- Half of all flood modification measures were related to detention basins, such as:
 - Increase capacity
 - Upgrade for basin safety
 - Remove trees from embankments
 - Include basins in Asset Management Strategy













- High A Consequence Category
- Capacity 208ML
- Spills over embankment in 1% AEP event





- Remove 100 trees from embankment
- Raise embankment to contain 1% AEP

- High A need to pass PMF
- BSC Pass 1 in 1000 year
- 290m reinforced turf spillway
- Debris control structure






Issues:

- Removal of trees Biodiversity Conservation Act
- Aboriginal Heritage
- Contamination
- Lime stabilisation
- Chain for debris control structure
- Stakeholders










Completed works



2. Mimosa Road Detention Basin



- High C consequence category
- Capacity 45ML
- Spills over embankment in 5% AEP event




2. Mimosa Road Detention Basin




- Raise embankment to contain 1% AEP
- High C need to pass 1 in 100,000
- BSC pass 1 in 500 year
- 196m reinforced turf spillway
- Replace existing Ø2450mm pipe under road with a 2400(H) x 3000(W) box culvert
- Energy dissipation downstream baffle blocks
- Sydney Water Ø1350mm main bridging slab













Issues:

- Contamination
- Sydney Water Ø1350mm main
- Endeavor Energy
- Rainfall events delays and rework
- Variations cost and time
- Managing expectations traffic, sporting clubs, pedestrians

Works scheduled to finish in May 2026






3. Stockdale Reserve Detention Basin





- Raise embankment to contain
 1% AEP
- High C need to pass 1 in 100,000
- 50m concrete and reinforced turf spillway
- Cut off wall to stop pond seepage
- Privacy screening





3. Stockdale Reserve Detention Basin








4. King Park Detention Basin



- Significant CC need to pass 1 in 10,000
- 120m reinforced turf spillway
- Tree removal
- Concrete footpath on crest



dCity ersty







Other dam safety measures

- Monthly dam inspections
- O&M Plans
- Emergency Plans
- Emergency exercises
- Dam break and CC assessments
- Risk Reports SFAIRP
- Basin maintenance
- DSMS continual improvement
- Annual reporting







Declared Dams - Flood Detention Basins

Leonie Gray

Igray@fairfieldcity.nsw.gov.au

(02) 9725 0222